



67652

EBASCO SERVICES INCORPORATED

160 Chubb Avenue, Lyndhurst, NJ 07071-3586

PHOTOGRAPH LOG BOOK
TEST PITTING OPERATIONS
SCIENTIFIC CHEMICAL PROCESSING SITE

EPA WORK ASSIGNMENT NUMBER: 11-2665.0
EPA CONTRACT NUMBER: 68-01-7250

EBASCO

10045 (LYN) 6-88

Address correction requested.
Return postage guaranteed.

001047

PHOTOGRAPH LOG
SCIENTIFIC CHEMICAL PROCESSING SITE
CARLSTADT, NEW JERSEY

<u>PHOTO NO</u>		<u>DESCRIPTION</u>	<u>TIME/DATE</u>
1	T1	View of Buried Drum	1005/07-20-89
2	T1	View of Wall	1035/07-20-89
3	T1	View of Wall	"
4	T1	View of Debris	"
5	T1	View of Debris	"
6	T2	View of Metal	1130/07-20-78
7	T2	View of Metal	"
8	T2	View of Pile and Hole	1135/07-20-89
9	T3	View of Cinderblock	1335/07-20-89
10	T3	View of Cinderblock	"
11	T3	View of Oil in Hole	1341/07-20-89
12	T3	View of Oil in Hole	"
13	T3	View of Wall	1350/07-20-89
14	T3	View of Wall	"
15	T3	View of Debris	"
16	T4	Layer of Brick	1415/07-20-89
17	T4	View of Wall	1430/07-20-89
18	T4	View of Wall	"
19	T4	View of Debris	"
20	T4	View of Wall	"
21	T4	View of Wall	1433/07-20-89
22	T4	View of Debris	"
23	T4	View of Debris	"
24	T5	(No Photo Available)	1505/07-20-89
25	T6	View of SE Wall	0846/07-21-89
26	T6	North View of Debris	"
27	T6	SE View of Foam being sprayed on T6	"
28	T7	View of SE Wall	0935/07-21-89
29	T7	View of SE Wall	"
30	T7	NW View of Debris	"
31	T8	NE View of Oil in Hole	1050/07-21-89
32	T8	NE View of Debris	1105/07-21-89
33	T8	SW View of Debris	"
34	T8	View of NW Wall	"
35	T8	View of NW Wall	"
36	T9	View of SE Wall	1130/07-21-89
37	T9	SE View of Pit	"
38	T9	SE View of Debris	"
39	T9	SE View of Debris	55/07-21-89
40	T9	NE View of Pit	"

001048

<u>PHOTO NO</u>		<u>DESCRIPTION</u>	<u>TIME/DATE</u>
41	T10	View of SE Wall	1515/07-21-89
42	T10	NW View of Debris	"
43	T11	View of SE Wall	1545/07-21-89
44	T11	View of NW Wall	"
45	T11	SE View of Debris	"
46	T12	View of SE Wall	1020/07-24-89
47	T12	View of SE Wall	"
48	T13	SW View of Debris	1055/07-24-89
49	T13	SW View of Debris	1100/07-24-89
50	T13	View of W Wall	"
51	T13	View of SE Wall	"
52	T14	View of NE Wall	1230/07-24-89
53	T14	View of Debris at T14	"
54	T15	NE View of Debris	1310/07-24-89
55	T15	View of SE Wall	"
56	T16	SE View of Debris	1400/07-24-89
57	T16	View of NE Wall	"
58	T17	View of SW Wall	1725/07-24-89
59	T17	SE View of Debris	"
60	T18	SE View of Debris	1810/07-24-89
61	T18	View of E Wall	"
62	T19	View of SE Wall	1850/07-24-89
63	T19	NE View of Debris	"
64	T20	View of SE Wall	1905/07-24-89
65	T20	SE View of Debris	"
66	T21	View of SE Wall	0916/07-25-89
67	T21	SE View of Debris	"
68	T22	View of SE Wall	0930/07-25-89
69	T22	SE View of Debris	"
70	T23	SE View of Debris	1105/07-25-89
71	T23	View of SE Wall	"

001049



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 1

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1005 HRS

TEST PIT NO. T1

TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT 5-10% GRAVEL

2-4 FT DRUM, ROCK FRAGMENTS (4-6 IN.)

4-6 FT BRICK

6-8 FT BRICK, SHINGLES @ 7 FT

VIEW OF NORTH WEST WALL

001050

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 2

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1035 HRS

TEST PIT NO. T1

TOTAL DEPTH 8 FT

DESCRIPTION

(SAME AS PHOTO NO. 1)

001051

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 3

PHOTOGRAPHER D.WENDT

DATE 7/20/89

TIME 1035 HRS

TEST PIT NO. T1

TOTAL DEPTH 8 FT

DESCRIPTION

(SAME AS PHOTO NO. 1)

001052

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 4

PHOTOGRAPHER D.WENDT

DATE 7/20/89

TIME 1035 HRS

TEST PIT NO. T1

TOTAL DEPTH 8 FT

DESCRIPTION (SAME AS PHOTO NO. 1)
NORTH WEST VIEW OF DEBRIS PILE

001053

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 5 PHOTOGRAPHER D. WENDT

DATE 7/20/89 TIME 1035 HRS

TEST PIT NO. T1 TOTAL DEPTH 8 FT

DESCRIPTION (SAME AS PHOTO NO. 1)
NORTH WEST VIEW OF DEBRIS

001054

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 6

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1130 HRS

TEST PIT NO. T2

TOTAL DEPTH 2 FT

DESCRIPTION 0-2 FT. 10-15% GRAVEL, 45% WOOD (2X4),
AND BRICK FRAGMENTS AT 1 FT.
PIT FILLED WITH FOAM DUE TO
HIGH VOLATILES.
VIEW OF NORTH WEST WALL

001055

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 7 PHOTOGRAPHER D. WENDT

DATE 7/20/89 TIME 1130

TEST PIT NO. T2 TOTAL DEPTH 2 FT

DESCRIPTION (SAME AS PHOTO NO. 6)

001056

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 8

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1135 HRS

TEST PIT NO. T2

DESCRIPTION

(SAME AS PHOTO NO. 6)

NORTH WEST VIEW OF PIT

001057

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 9 PHOTOGRAPHER D. WENDT

DATE 7/20/89 TIME 1335 HRS

TEST PIT NO. T3 TOTAL DEPTH 8 FT

DESCRIPTION 0-2 FT. 10-15% GRAVEL, 5% CINDERBLOCK
AND ROCK FRAGMENTS
2-4 FT. 10% BRICK AND ROCK FRAGMENTS
4-6 FT. 30% BRICK AND SHINGLE, BOULDER
(APPROX. 1 FT. IN LENGTH)
6-8 FT. DRIED OIL
NORTH WEST VIEW OF PIT

001058

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 10

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1335 HRS

TEST PIT NO. T3

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 9)

001059

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 11 PHOTOGRAPHER D. WENDT

DATE 7/20/89 TIME 1341 HRS

TEST PIT NO. T3 TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 9)

001060

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 12

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1341 HRS.

TEST PIT NO. T3

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 9)

001061

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 13

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1350 HRS

TEST PIT NO. T3

DESCRIPTION

(SAME AS PHOTO NO. 9)

001062

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 14

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1350 HRS

TEST PIT NO. T3

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 9)

001063

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 15 PHOTOGRAPHER D. WENDT

DATE 7/20/89 TIME 1350 HRS

TEST PIT NO. T3

DESCRIPTION

(SAME AS PHOTO NO. 9)

001064

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 16

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1415 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 10-15% GRAVEL
2-4 FT. BRICK AND CINDERBLOCK FRAGS.
4-6 FT. METAL PIPE (1 IN. DIA.),
5-10% GRAVEL
6-8 FT. OIL SOAKED SHINGLES, PEAT
@ 8 FT.
VIEW OF NORTH WEST WALL

001065

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 17

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1430 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 16)

001066

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 18

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1430 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 16)

VIEW OF SOUTH EAST WALL

001067

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 19

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1430 HRS

TEST PIT NO. T4

DESCRIPTION

(SAME AS PHOTO NO. 16)

SOUTH EAST VIEW OF DEBRIS PILE

001068

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 20

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1430 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.


DESCRIPTION

(SAME AS PHOTO NO. 16)

VIEW OF SOUTH EAST WALL

001069

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 21

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1433 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 16)

001070

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 22

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1433 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 16)

SOUTH EAST VIEW OF DEBRIS PILE

001071

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 23

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1433 HRS

TEST PIT NO. T4

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 16)

001072

EBASCO

NO PHOTOGRAPH AVAILABLE

SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 24

PHOTOGRAPHER D. WENDT

DATE 7/20/89

TIME 1505 HRS

TEST PIT NO. T5

TOTAL DEPTH 8 FT.

DESCRIPTION	<u>0-2 FT. 15-20% GRAVEL</u>
	<u>2-4 FT. BRICK FRAGMENTS</u>
	<u>4-6 FT. BOULDER (1 FT. DIA.), STEEL</u>
	<u>I BEAM</u>
	<u>6-8 FT. SHINGLES</u>

001073

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 25

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 0846 HRS

TEST PIT NO. T6

TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 15% GRAVEL

2-4 FT. 90% GRAVEL, CINDERBLOCK FRAGS.

4-6 FT. BRICK FRAGMENTS

6-8 FT. SHINGLES

VIEW OF SOUTH EAST WALL

001074

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 26

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 0846 HRS

TEST PIT NO. T6

DESCRIPTION

(SAME AS PHOTO NO. 25)

VIEW OF DEBRIS PILE

001075

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 27 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 0846 HRS

TEST PIT NO. T6 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 25)
VIEW FROM SOUTH EAST AS FOAM IS
BEING APPLIED

001076

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 28

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 0935 HRS

TEST PIT NO. T7

TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 25% GRAVEL
2-4 FT. 3-4 IN. LAYER OF OIL, 5% ROCK
FRAGMENTS
4-6 FT. 25% BRICK, BOULDER (1 FT DIA.)
STEEL PIPE (2 IN. X 8 FT.)
6-8 FT. 30% BRICK @ 7 FT., 70% SHINGLE
VIEW OF SOUTH EAST WALL

001077

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 29 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 0935 HRS

TEST PIT NO. T7 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 28)

001078

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 30

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 0935 HRS

TEST PIT NO. T7

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 29)

NORTH WEST VIEW OF DEBRIS PILE

001079

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 31 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1050 HRS

TEST PIT NO. T8 TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 20% GRAVEL, 5% ROCK FRAGMENTS
2-4 FT. CONCRETE SLAB, METAL LID,
BRICK FRAGMENTS, BOULDER
4-6 FT. 5% WOOD, 30% BRICK
6-8 FT. BRICK, SHINGLES @ 7 FT.
NORTH EAST VIEW OF TEST PIT

001080

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 32

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1105 HRS

TEST PIT NO. T8

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 31)

NORTH EAST VIEW OF DEBRIS PILE

001081

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 33 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1105 HRS

TEST PIT NO. T8 TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 31)

SOUTH EAST VIEW OF DEBRIS PILE

001082

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 34

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1105 HRS

TEST PIT NO. T8

TOTAL DEPTH 8 FT.


DESCRIPTION

(SAME AS PHOTO NO. 31)

VIEW OF NORTH WEST WALL

001083

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 35 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1105 HRS

TEST PIT NO. T8 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 31)

001084

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 36

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1130 HRS

TEST PIT NO. T9

TOTAL DEPTH 6 FT.

DESCRIPTION 0-2 FT. 15-20% GRAVEL, 5% ROCK FRAGS.
2-4 FT. CONCRETE PAD (6-8 IN. THICK),
LAYER OF CRUSHED DRUMS
4-6 FT. 50% BRICK, 10% ROCK FRAGMENTS
VIEW OF SOUTH EAST WALL

001085

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 37 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1130 HRS

TEST PIT NO. T9 TOTAL DEPTH 6 FT.

DESCRIPTION

(SAME AS PHOTO NO. 36)

SOUTH EAST VIEW OF TEST PIT

001086

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 38

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1130 HRS

TEST PIT NO. T9

TOTAL DEPTH 6 FT.

DESCRIPTION

(SAME AS PHOTO NO. 36)

SOUTH EAST VIEW OF DEBRIS PILE

001087

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 40

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1155 HRS

TEST PIT NO. T9

TOTAL DEPTH 6 FT.

DESCRIPTION

(SAME AS PHOTO NO. 36)

NORTH EAST VIEW OF TEST PIT

001089

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 41 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1515 HRS

TEST PIT NO. T10 TOTAL DEPTH 4 FT.

DESCRIPTION 0-2 FT. 10-15% GRAVEL
2-4 FT. 15-20% BRICK AND ROCK FRAGS.

VIEW OF SOUTH EAST WALL

001090

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 42

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1515 HRS

TEST PIT NO. T10

TOTAL DEPTH 4 FT.

DESCRIPTION

(SAME AS PHOTO NO. 41)

NORTH WEST VIEW OF DEBRIS PILE

001091

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 43 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1545 HRS

TEST PIT NO. T11 TOTAL DEPTH 7 FT.

DESCRIPTION 0-2 FT. 10% GRAVEL, 5% ROCK, BOULDERS
(2 @ 1-1 FT. DIAMETER EACH)
2-4 FT. 55% WOOD, SOME METAL STRAPS
4-6 FT. WOOD AND BRICK FRAGMENTS
6-7 FT. PEAT LAYER
VIEW OF SOUTH EAST WALL

001092

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 44

PHOTOGRAPHER D. WENDT

DATE 7/21/89

TIME 1545 HRS

TEST PIT NO. T11

TOTAL DEPTH 7 FT.

DESCRIPTION

(SAME AS PHOTO NO. 43)

VIEW OF NORTH WEST WALL

001093

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 45 PHOTOGRAPHER D. WENDT

DATE 7/21/89 TIME 1545 HRS

TEST PIT NO. T11 TOTAL DEPTH 7 FT.

DESCRIPTION (SAME AS PHOTO NO. 43)
SOUTH EAST VIEW OF DEBRIS PILE

001094

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 46

PHOTOGRAPHER D. WENDT

DATE 7/24/89

TIME 1020 HRS

TEST PIT NO. T12

TOTAL DEPTH 6 FT.

DESCRIPTION 0-2 FT. 10-15% GRAVEL, 10% CINDERBLOCK
2-4 FT. 15-20% BRICK FRAGMENTS
4-6 FT. 50% BRICK AND ROCK FRAGMENTS
VIEW OF SOUTH EAST WALL

001095

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 48

PHOTOGRAPHER D. WENDT

DATE 7/24/89

TIME 1055 HRS

TEST PIT NO. T13

TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 5-10% GRAVEL

2-4 FT. 25% WOOD, 15-20% BRICK FRAGS.

4-6 FT. 50% ROCK FRAGS., 15% BOULDER

6-8 FT. 10% BOULDER (1.5 FT. DIA.)

SOUTH WEST VIEW OF DEBRIS PILE

001096

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 49 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1100 HRS

TEST PIT NO. T13 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 48)

001097

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 50 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1100 HRS

TEST PIT NO. T13 TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 48)

VIEW OF WEST WALL OF TEST PIT

001098

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 51 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1100 HRS

TEST PIT NO. T13 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 48)
VIEW OF SOUTH EAST WALL

001099

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 52 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1230 HRS

TEST PIT NO. T14 TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 15-20% GRAVEL
2-4 FT. 50% ROCK FRAGMENTS
4-6 FT. 50% ROCK FRAGMENTS
6-8 FT. 50% ROCK FRAGMENTS
VIEW OF NORTHEAST WALL

001100

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 54 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1310

TEST PIT NO. T15 TOTAL DEPTH 8 FT.

DESCRIPTION 0-2 FT. 5-10% GRAVEL
2-4 FT. BRICK FRAGMENTS
4-6 FT. BOULDERS (3 @ 1-3 FT. DIA.)
6-8 FT. CONCRETE SLABS
NORTH EAST VIEW OF DEBRIS PILE

001102

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 55 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1310 HRS

TEST PIT NO. T15 TOTAL DEPTH 8 FT.

DESCRIPTION (SAME AS PHOTO NO. 54)
VIEW OF SOUTH EAST WALL

001103

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 56 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1400 HRS

TEST PIT NO. T16 TOTAL DEPTH 4.5 FT.

DESCRIPTION 0-2 FT. 10-15% GRAVEL, 5% ROCK FRAGS.
2-4 FT. 40% ROCK FRAGMENTS
4-4.5 FT 40% ROCK FRAGMENTS
SOUTH EAST VIEW OF DEBRIS PILE

001104

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 57

PHOTOGRAPHER D. WENDT

DATE 7/24/89

TIME 1400 HRS

TEST PIT NO. T16

TOTAL DEPTH 4.5 FT.


DESCRIPTION

(SAME AS PHOTO NO. 56)

NORTH EAST WALL OF TEST PIT

001105

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 58 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1725 HRS

TEST PIT NO. T17 TOTAL DEPTH 2 FT.

DESCRIPTION 0-2 FT. 25% GRAVEL, CONCRETE SLAB
@ 1 FT.

SOUTH WEST WALL OF TEST PIT

001106

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 59

PHOTOGRAPHER D. WENDT

DATE 7/24/89

TIME 1725 HRS

TEST PIT NO. T17

TOTAL DEPTH 2 FT.

DESCRIPTION

(SAME AS PHOTO NO. 58)

SOUTH EAST VIEW OF DEBRIS PILE

001107

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 60 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1810 HRS

TEST PIT NO. T18 TOTAL DEPTH 3.5 FT.

DESCRIPTION 0-2 FT. 15% GRAVEL, CONCRETE SLAB @
1 FT. (10 IN. THICK)
2-3.5 FT. BRICK FRAGMENTS
SOUTH EAST VIEW OF DEBRIS PILE

001108

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 62 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1850 HRS

TEST PIT NO. T19 TOTAL DEPTH 4 FT.

DESCRIPTION 0-2 FT. 5-10% GRAVEL
2-4 FT. 5-10% GRAVEL, CONCRETE SLAB
@ 2.5 FT.
VIEW OF SOUTH EAST WALL OF TEST PIT

001110

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 63

PHOTOGRAPHER D. WENDT

DATE 7/24/89

TIME 1850 HRS

TEST PIT NO. T19

TOTAL DEPTH 8 FT.

DESCRIPTION

(SAME AS PHOTO NO. 62)

NORTH EAST VIEW OF DEBRIS PILE

001111

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 64 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1905 HRS

TEST PIT NO. T20 TOTAL DEPTH 4.5 FT.

DESCRIPTION 0-2 FT. 15-20% GRAVEL, 5% WOOD
2-4.5 FT 10-20% GRAVEL, 5% WOOD, SOME
METAL
VIEW OF SOUTH EAST WALL OF TEST PIT

001112

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 65 PHOTOGRAPHER D. WENDT

DATE 7/24/89 TIME 1905 HRS

TEST PIT NO. T20 TOTAL DEPTH 4.5 FT.

DESCRIPTION (SAME AS PHOTO NO. 64)
SOUTH EAST VIEW OF DEBRIS PILE

001113

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 66 PHOTOGRAPHER D. WENDT

DATE 7/25/89 TIME 0916 HRS

TEST PIT NO. T21 TOTAL DEPTH 4.5 FT.

DESCRIPTION 0-2 FT. 10-15% GRAVEL
2-4.5 FT. 10-15% GRAVEL, 10% WOOD, AND
METAL
VIEW OF SOUTH EAST WALL

001114

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 67 PHOTOGRAPHER D. WENDT

DATE 7/25/89 TIME 0916 HRS

TEST PIT NO. T21

DESCRIPTION (SAME AS PHOTO NO. 66)
SOUTH EAST VIEW OF DEBRIS PILE

001115

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 68 PHOTOGRAPHER D. WENDT

DATE 7/25/89 TIME 0930 HRS

TEST PIT NO. T22 TOTAL DEPTH 3.5 FT.

DESCRIPTION 0-2 FT. 15% GRAVEL, 5% ROCK FRAGMENTS
CONCRETE SLAB AT 1.5 FT.
(6-8 IN. THICK)
2-3.5 FT LAYER OF BRICK FRAGMENTS
VIEW OF SOUTH EAST WALL

0C1116

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 69

PHOTOGRAPHER D. WENDT

DATE 7/25/89

TIME 0930 HRS

TEST PIT NO. T22

TOTAL DEPTH 3.5 FT.

DESCRIPTION

(SAME AS PHOTO NO. 68)

SOUTH EAST VIEW OF DEBRIS PILE

001117

EBASCO



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 70 PHOTOGRAPHER D. WENDT

DATE 7/25/89 TIME 1105 HRS

TEST PIT NO. T23 TOTAL DEPTH 3 FT.

DESCRIPTION 0-2 FT. 15% GRAVEL, 5% BRICK
2-3 FT. LAYER OF BRICK FRAGMENTS, 5%
WOOD
VIEW OF SOUTH EAST WALL



SITE NAME : SCIENTIFIC CHEMICAL PROCESSING

LOCATION : CARLSTADT, NEW JERSEY

PHOTO NO. 71

PHOTOGRAPHER D. WENDT

DATE 7/25/89

TIME 1105 HRS

TEST PIT NO. T23

DESCRIPTION

(SAME AS PHOTO NO. 47)

SOUTH EAST VIEW OF DEBRIS PILE

001119

EBASCO